

Creep Deformation in Materials

Academic Resource Center

Agenda

- Define creep and discuss its importance in materials engineering.
- Identify the primary mechanisms of creep deformation.
- Creep model parameters.
- Detail experimental ways to determine creep.
- Discuss design options to minimize creep deformation.

Useful concepts revision...




FIGURE 6-10 The relationship between the true stress–true strain diagram and the engineering stress–engineering strain diagram.



FIGURE 6-4 Localized deformation of a ductile material during a tensile test produces a necked region.

$$\text{Engineering stress} = \sigma = \frac{F}{A_0}$$

$$\text{Engineering strain} = \varepsilon = \frac{l - l_0}{l_0}$$

$$\text{True stress} = \sigma_t = \frac{F}{A}$$


$$\text{True strain} = \varepsilon_t = \int_{l_0}^l \frac{dl}{l} = \ln\left(\frac{l}{l_0}\right) = \ln\left(\frac{A_0}{A}\right)$$

Creep

- It is a **time- dependent** deformation under a certain applied load.
- Generally occurs at **high temperature** (thermal creep), but can also happen at room temperature in certain materials (e.g. lead or glass), albeit much slower.
- As a result, the material undergoes a time dependent **increase in length**, which could be dangerous while in service.

Classical Creep Curve


- The rate of deformation is called the creep rate. It is the slope of the line in a Creep Strain vs. Time curve.





Creep Stages

- **Primary Creep**: starts at a rapid rate and slows with time.
- **Secondary Creep**: has a relatively uniform rate.
- **Tertiary Creep**: has an accelerated creep rate and terminates when the material breaks or ruptures. It is associated with both necking and formation of grain boundary voids.

Effect of Temperature & Stress



Effect of Individual Variable



Characteristics of Creep

- Creep in service is usually affected by changing conditions of loading and temperature
- The number of possible stress-temperature-time combinations is infinite.
- The creep mechanisms is often different between metals, plastics, rubber, concrete.

Creep Mechanisms

- Bulk Diffusion (Nabarro-Herring creep)
 - Creep rate decreases as grain size increases
- Grain Boundary Diffusion (Coble creep)
 - Stronger grain size dependence than Nabarro Herring
- Dislocation climb/creep
 - Controlled by movement of dislocations, strong dependence on applied stress.
- Thermally activated glide
 - Occurs in polymers and other viscoelastic materials

Creep Test

- Measures dimensional changes accurately at constant high temperature and constant load or stress.
- Useful for modeling long term applications which are strain limited.
- Provides prediction of life expectancy before service. This is important for example turbine blades.

Creep Test cont'd

- Measures strain vs. time at constant T and Load (Similar to graph seen previously).
- Relatively low loads and creep rate
- Long duration 2000 to 10,000 hours.
- Not always fracture.
- Strain typically less than 0.5%.


Creep Test cont'd

- Creep generally occurs at elevated temperatures, so it is common for this type of testing to be performed with an environmental chamber for precise heating/cooling control.
- Temperature control is critical to minimize the effects of thermal expansion on the sample.

Creep Test: General Procedure

- The unloaded specimen is first heated to the required T and the gage length is measured.
- The predetermined load is applied quickly without shock.
- Measurement of the extension are observed at frequent interval.
- Average of about 50 readings should be taken.

Creep Test Apparatus



Creep Parameters

- To predict the stress and time for long lives on the basis of much shorter data.
- Plant life 30 to 40 years
- Creep data is usually not available beyond lives of more than 30000 hrs.
- Larson Miller Parameter and other material specific models are used.

Larson Miller Parameter

- Model based on Arrhenius rate equation.

$$LMP = T(C + \log t_r)$$

Where T = temperature (K or °R)

t_r = time before failure (hours)


C = material specific constant

- Predicts rupture lives given certain temperature and stress.
- First used by General Electric in the 50's to perform research on turbine blades.

Stress Rupture Tests

- Determines the time necessary for material to result in failure under a **overload**.
- Useful in materials selection where dimensional tolerances are acceptable, but **rupture cannot be tolerated**.
- Generally performed at elevated temperatures.
- Smooth, notched, flat specimens or samples of any combination can be tested.

Creep vs. Stress Rupture Test



- Low Loads
- Precision Strain Measurement ($\epsilon_f < 0.5\%$)
- Long term (2000-10,000 h)
- Expensive equipment

Emphasis on minimum strain rate at stress and temperature

- High Loads
- Gross Strain Measurement (ϵ_f up to 50%)
- Short term (<1000 h)
- Less expensive equipment

Emphasis on time to failure at at stress and temperature

Design Considerations to avoid Creep

- Reduce the effect of grain boundaries:
 - Use single crystal material with large grains.
 - Addition of solid solutions to eliminate vacancies.
- Employ materials of high melting temperatures.
- Consult Creep Test Data during materials Selection
 - Type of service application
 - Set adequate inspection intervals according to life expectancy.

References

- Abbaschian, Reed-Hill. “Physical Metallurgy Principles”. 4th edition. 2009
- Dowling, Norman E. Mechanical Behavior of Materials. 3rd edition. 2007
- “Larson Miller Parameter”
<http://www.twi.co.uk/technical-knowledge/faqs/material-faqs/faq-what-is-the-larson-miller-parameter/>